

72301X^{Q&As}

Avaya Aura Communication Applications Support Certified Exam

Pass Avaya 72301X Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.geekcert.com/72301x.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Avaya
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



VCE & PDF GeekCert.com

https://www.geekcert.com/72301x.html

2024 Latest geekcert 72301X PDF and VCE dumps Download

QUESTION 1

After a new implementation the customer began to experience dropped calls and an `all lines busy\\' error condition. The carrier confirmed their service was operational and all lines tested came back good. After contacting Avaya, support confirmed there were more calls being presented than the telephone switch could handle.

confirmed there were more calls being presented than the telephone switch could handle.	
Which pre-implementation step was omitted?	

B. interoperability testing

A. properly sizing trunk capacity

2. moreperasinty teeming

C. upgrading the circuits

D. correct licensing specifications

Correct Answer: A

QUESTION 2

A customer reports that they cannot place WebRTC calls. You discover there is a problem with communication between Avaya Breeze TM and the Avaya Aura Media Server (AAMS). Where in Avaya Breeze TM do you set/check the User ID for Restful TLS authentication?

A. Use the System Manager (SMGR) web GUI to access Breeze > Configuration > Avaya Aura Media Server

B. Use the System Manager (SMGR) web GUI to access Breeze > Cluster Administration > General > Cluster Attributes

C. Use the System Manager (SMGR) web GUI to access Breeze > Configuration > Attributes

D. Use the System Manager (SMGR) web GUI to access Breeze > Server Administration > Dashboard


Correct Answer: B

QUESTION 3

Refer to the exhibit.

https://www.geekcert.com/72301x.html

2024 Latest geekcert 72301X PDF and VCE dumps Download



In the Cluster Administration screen of a PresenceServices cluster, when you try to change the cluster state to Accept New Service, you receive the error:

Servers that are not in License Restricted mode assigned to the cluster are below the Minimum number of required servers.

You check that a server has been administered under Breeze > Server Administration which shows green check under License Mode, and a System State of Denying.

Which action needs to be taken to solve this problem?

A. Edit the Cluster, access the Servers tab, and assign the server to the cluster; then set the cluster to Accept New Service.

- B. Under Avaya Breeze > Server Administration, select the server and change the System State to Accept New Service, then return to the Cluster Administration screen and set the cluster to Accept New Service.
- C. Obtain and install an Avaya BreezeTM license on webLM with more instances of Avaya BreezeTM nodes.
- D. Edit the cluster to change the cluster profile from Core Platform to General Purpose.

Correct Answer: B

QUESTION 4

What are two valid Avaya Aura Messaging (AAM) Measurement Report types? (Choose two.)

- A. Occupancy
- B. Load
- C. Users



https://www.geekcert.com/72301x.html 2024 Latest geekcert 72301X PDF and VCE dumps Download

D. Disk Usage

E. Feature

Correct Answer: BE

Reference:https://downloads.avayA.com/css/P8/documents/100166431(page 289)

QUESTION 5

Avaya Aura Messaging (AAM) needs to communicate with Avaya Aura Session Manager (SM) whose identity certificates have been signed by Avaya Aura System Manager (SMGR) Certificate Authority (CA). How does AAM get a copy of the Trusted SMGR CA Certificate?

- A. The certificate is retrieved from SMGR automatically when AAM services are started.
- B. The certificate needs to be manually installed.
- C. The certificate installs as a result of running `initTM

Correct Answer: B

72301X VCE Dumps

72301X Exam Questions

72301X Braindumps